



**GENERAL FILTERS**  
INCORPORATED

**GeneralAire® Vapor Pad®**  
990-13

**990-13**  
(GFI #7002)

**Replacement for Whole-House Legacy Humidifiers:  
709, 990, 1040, 1042, 1137, & SL16**

- Coated metal pad offers optimal water absorption and humidification
- Replace once per year for maximum performance of your humidifier
- Replacement instructions are located on the reverse side; or by using the QR Code at right to watch a video demonstration
- Ideal humidity level is between 40-60%
- 12" H x 9 3/4" W x 1 1/2" D



Not all models shown.  
Model 1042LH pictured above.

Are you concerned that too much water is going down the drain?

**Install the GeneralAire® Water Savor™ Controller**



**Save Water**  
**Save Money \$\$\$**  
**Save the Environment**

- Reduce water going down the drain from your humidifier by a minimum of 50%
- Realize *maximum* results with customized settings
- Install with any model (new or existing) bypass, flow-through humidifiers  
\*\*Not compatible with fan-powered or steam humidifiers
- Learn more: Use the QR Code to watch our Water Savor™ Controller video on [www.generalfilters.com](http://www.generalfilters.com) / Support Center / Video Library



**Maintenance Instructions:**

**Change your Vapor Pad® once each year.**



General Filters, Inc.  
43800 Grand River Avenue  
Novi, Michigan 48375  
Toll Free: (866) 476-5101  
[www.generalaire.com](http://www.generalaire.com)



Canadian General Filters, Ltd.  
400 Midwest Rd.  
Toronto, ON M1P3A9 Canada  
Toll Free: (888) 216-9184  
[www.cgfproducts.com](http://www.cgfproducts.com)

